PRELIMINARY SUMMARY OF MAP ACTIONS

Community: CLINTON COUNTY Community No: 180029

To assist your community in maintaining the Flood Insurance Rate Map (FIRM), we have summarized below the previously issued Letter of Map Change (LOMC) actions (i.e., Letters of Map Revision (LOMRs) and Letters of Map Amendment (LOMAs)) that will be affected by the preparation of the enclosed revised FIRM panel(s).

1. LOMCs Incorporated

The modifications effected by the LOMCs listed below have been reflected on the Preliminary copies of the revised FIRM panels. In addition, these LOMCs will remain in effect until the revised FIRM becomes effective.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
			NO CASES RECORDED		

2. LOMCs Not Incorporated

The modifications effected by the LOMCs listed below have not been reflected on the Preliminary copies of the revised FIRM panels because of scale limitations or because the LOMC issued had determined that the lot(s) or structure(s) involved were outside the Special Flood Hazard Area, as shown on the FIRM. These LOMCs will be revalidated free of charge 1 day after the revised FIRM becomes effective through a single revalidation letter that reaffirms the validity of the previous LOMCs.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMA	199108209FIA	09/23/1991		0004B	18023C0295C
LOMA	03-05-2009A	05/09/2003	A PORTION OF SECTION 20, T23N, R2W, SECOND PRINCIPAL MERIDIAN; 8696 WEST STATE ROAD 26	1800290001B	18023C0020C
LOMA	08-05-2904A	05/22/2008	4119 NORTH 180 EAST PORTION OF SECTION 13, T22N, R1W	1800290001B	18023C0155C
LOMA	09-05-1097A	01/27/2009	PORTION OF SECTION 28, T22N, R2W 7707 WEST MULBERRY JEFFERSON ROAD	1800290001B	18023C0110C
LOMA	09-05-1298A		9950 NORTH COUNTY ROAD 600 WEST PORTION OF SECTION 22, T23N, R2W	1800290001B	18023C0020C

3. LOMCs Superseded

The modifications effected by the LOMCs listed below have not been reflected on the Preliminary copies of the revised FIRM panels because they are being superseded by new detailed flood hazard information or the information available was not sufficient to make a determination. The reason each is being superseded is noted below. These LOMCs will no longer be in effect when the revised FIRM becomes effective.

4/7/2010 Page 1 of 2

PRELIMINARY SUMMARY OF MAP ACTIONS

Community: CLINTON COUNTY Community No: 180029

LOMC	Case No.	Date Issued	Project Identifier	Reason Determination Will be Superseded
			NO CASES RECORDED	

- 1. Insufficient information available to make a determination.
- 2. Lowest Adjacent Grade and Lowest Finished Floor are below the proposed Base Flood Elevation.
- 3. Lowest Ground Elevation is below the proposed Base Flood Elevation.
- 4. Revised hydrologic and hydraulic analyses.
- 5. Revised topographic information.

4. LOMCs To Be Redetermined

The LOMCs in Category 2 above will be revalidated through a single revalidation letter that reaffirms the validity of the determination in the previously issued LOMC. For LOMCs issued for multiple lots or structures where the determination for one or more of the lots or structures has changed, the LOMC cannot be revalidated through this administrative process. Therefore, we will review the data previously submitted for the LOMC requests listed below and issue a new determination for the affected properties after the effective date of the revised FIRM.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
			NO CASES RECORDED		

4/7/2010 Page 2 of 2